

Blue Ink - PCO  
Red Ink - Ith - Acoustic

DATE	Location	Type of Houses Construction	Observer
8/14/01 8/17/01	K. L. Malaysia	Bungalow --- 1 Flag --- 4  All walls are concrete + wooden frame + wood attic + wood parquet ceiling + wooden door	TR. Not much detection Monotone yes
8/20/01 8/21/01	Penang Malaysia	Flag - 5  All wall - concrete + wooden frame + wooden door ceiling - concrete	All these houses has been treated with insecticide Larvae Dining own insecticide Above ground dirt were in place. Therefore termite has been somewhat deterred and disappeared. As a result they did not get together in big groups & made tunnels. In some cases to get them it also due to the high humidity. Put Acoustic and pick up their activities sound

Above 10 houses: PCO already ~~saw~~ knows the  
presence of termite.  
Therefore I am not  
going to include these  
houses into my studies

Date	Location	Type of House Construction	Observation
9/18/01	Portola	US type construction about 2000 ft <sup>2</sup> Took 20 min to locate termites & about 1 hr to check the whole house. 2 stone <sup>suspected spots</sup> <sup>confirmed spots</sup> PCO: miss <sup>20 per square foot</sup> WE: found <sup>3</sup>	Termites detected! Took only 20 mins. IR also detected other nest marks which was confirmed by dry wall and PCO call me to check the spot to tell me the location but I said I can find it
9/17/01	Oxford Richard Hadden 1721	US type construction about 2000 ft <sup>2</sup> Took 1 hr to inspect the whole house. 2 stones <sup>suspected spots</sup> <sup>confirmed spots</sup> PCO: NO <sup>20 per square foot</sup> WE: YES <sup>3</sup>	Termites detected in the garage area, above the door But also detected many inspection spots but didn't confirm NO termites.
9/28/01	Tupelo (fillmore) PCO: NO (twice) WE: YES	US type <sup>suspected spots</sup> <sup>confirmed spots</sup> one story <sup>20 per square foot</sup> about 1700 ft <sup>2</sup> PCO: NO (twice) WE: YES <sup>found termites in 2 minutes</sup>	"Termites reinfestation" This house was treated one year ago with Sentron & spray the suspected spot with permethrin 75 but the house 2 months later owner called twice said she can hear termite activities so I did not find any there. He called me to check. It took 2 minutes to locate termites in that room. (just check that room)
10/4/01	Oxford Dr. Brezede suspected spots: 3 confirmed spots: 1	US type one story about 1750 ft <sup>2</sup>	"Termites detected" found termite in the garage door weather trim 1 hr to check the whole house

DATE	LOCATION	Type of House Construction	Observations
8/22/01	Singapore	2 story Bungalow - ① - <del>Yes</del> 2 stories Semi detach - ② - <del>Yes</del>	IR - <del>Yes</del> (quite obvious)
8/27/01	WE: Yes	Concrete wall Wood Roof + Clay Roof Ceiling Wood products	Acoustic - yes (very loud)
8/27/01	One room home. IR suspected spot: 2 IR Confir spot: 1 Bungalow (Ant's mound) Found termite on the stairs. Case 3rd step Pkg Ant home (88 Jth parking) IR suspected spots: 2 IR Confir spots: 2 No pcc superim spot: 3 No spot pcc confir: 0 Oxford	My mother home has monthly inspection found termite at lower sect. of door frame. Pkg ant (light hill crast) IR suspected spot: 1 IR Confir spot: 1	None of the house has been treated in the passed 26 months
8/27/01	ISOM Building	Big old Historical building. A big house about 4500 ft <sup>2</sup> about 1 1/2 hr to check	NO Termite
	WE: NO PCC: NO (1st floor in Termites)	U.S. Type Construction 12 stories	The house has termite control and is quarantined to 1 inch deep drillers. The termite control no 55000/yr they spray with PCC 75 or fl
8/27/01	Oxford Pkg of B.C. suspected spot 0 Confir spot 0 WE: NO PCC: NO No pcc superimpts: 0 No pcc confir: 0	New building about 5 years old 3700 ft <sup>2</sup> to check for termites took about 1 1/2 hr to inspect	what cream spots outside No termite.
		U.S. Type Construction 2 stories	

1/15/74	Rolling Hill (Oxford)	Craig Hickey Suspected spots: 3 Confine spots: 0 # of spots per suspect: 0 # of spots per confine: 0	Many nice tanner in the ceiling but No tanner both IR & A camera
2/9	pro ND We: Yes suspected spots: 3 Confine spots: 2 # of spots per suspect: 0 # of spots per confine: 0	Sarah Davis house after I found tanager Kitchen Sarah Davis called up the post about to come & replace the board House was under renovation in Sept when the card board was removed located in Dan collected 3200 yr suspected spots: 1 Confine spots: 1 # of specimens set by pro: 0 # of spots per confine: 0 Ted Smith	Three spots of wet area acoustic sensor picking up in 2 close locati: in the house wall House has Sardinian in place since last year
2/24	wood land hill 10:30 - 11:00 pro: Yes We: Yes	in the master bed room wall suspected spots: 3 Confine spots: 1 # of spots per suspect: 0 # of spots per confine: 0	IR did pick up a wet spot and acoustic sensor pick up some sand in the kitchen & living room wall low range 3000 + ft house has a few Sardinian spot # of spots per suspect: 0 # of spots per confine: 0
4/24	pro: ND We: Yes	Jane's house Suspected spots: 0 Confine spots: 1 (by Acoustic) # of spots per suspect: 0 # of spots per confine: 0	IR did not detect any acoustic - perhaps tanager not in the kitchen area singing
5/24	Lakeview garden pro: ND We: Yes	Eric Fairbanks Small cabin suspected spots: 3 Confine spots: 2 # of spots per suspect: 6 # of spots per confine: 1	IR - see spots Acoustic: Yes
5/6	Near Square pro: ND We: Yes		

## Report

PCO  
Suspected  
for him

Home Soft  
Confirm  
position

2002

8/2

Kenny's Home

Tara Estate

We: No

P/O: No

spots suspected: 3  
confirm spots: 0  
PCO suspected spot: 0  
PCO confirm spot: 0

8/19

we: yes (Porter ID)  
P/O: No

Karan Muller  
Bruce Miller

Suspected spots: 4  
Confirm spots:  
PCO suspected spot: 0  
# spots PCO Conf: 0

8/20

we: yes (Porter ID)  
PCO: old boy. yes

Andy H. Perkins  
Hwy 7 North  
Suspected spots: 8  
Confirm spots: 4  
PCO suspected spots: 6  
# spots PCO confirm: 2

1/20

we: No  
P/O: No

Jim McClure  
Camp Ground Road  
Suspected spots: 2  
Confirm spots: 0

PCO suspected spots: 0  
# spots PCO Conf: 0

Total # of  
Suspected spots  
141

Total # of  
Confirm spots  
50

Total: 44

by WA: 30

by PCO: 12

House in Coastal Pk.

## Actual Confirmation

PCO  
suspected

Home Soft  
Suspected spots  
+ # spots  
confirm

PCO Suspected	Home Soft Confirm
49	6

2002

2002  
3/68NE of Tupelo  
10 miles

We: Yes

in kitchen - but  
not in the living roomPCO: Yes on  
old damage in living room  
not on life tent  
But no more life tent  
in the living room

3/28

Potatoes

We: NO

PCO: NO (100%)

IR found some  
Suspectia spots but  
Averilia in the room

\* if Suspectia spot: 1

\* if Conf. by PCO: 0 (old exit in allid)

3/28

Betula Potatoes  
S New Alber

We: NO

PCO: NO

IR found some  
Suspectia spots

\* if Suspectia spot: 1

\* if Conf. by PCO: 0 (old exit part)

Not coming M.O. 20

Total: 40

We: 28

PCO: 12

Tent chens - through  
Sheet Rock in the living  
roomHouse was treated with  
Serticon for more than  
half a yearBut no more life tent  
in living roomI found tent in the living  
portion of the wall in the  
kitchen - latter wall

Suspected spot: 4

Conf. : 1

\* if Suspectia spot: 1

\* if Conf. by PCO: 0 (old exit in allid)

House was baited with  
Serticon for a year2 year. but spring  
time (early march) there  
was a swamp of tent  
But I did not find any  
tent suspected spots: 3

Conf. : 0

House was baited  
Serticon for a yearbut has a swampy in  
early march. But I  
did not find any spot

Suspected spots: 4

Conf. : 0

part

part

Location

Rolling Hill  
(Oxford)

PCO No  
We No

PCO No

We Yes

suspected spots: 3

Confir spots: 2

# of spots PCO suspected: 0

# of spots PCO Confir: 0

Wood land with

o sign

10:30 - 11:00

PCO: Yes

We: Yes

PCO: ND

We: Yes

Lake wa.  
garden

PCO No

We Yes

Near Square

PCO No

We Yes

Coalg Hickory

Suspected spots: 3

Confir spots: 0

# of spots PCO suspected: 0

# of spots PCO Confir: 0

Sarah Davis house

also 2 found items

Kitchen Sarah Davis

called up the pest control

to come & replace

the bait

House was under renovation

in Sept when the card box

was removed

located in

200 ft

suspected spots: 1

Confir spots: 1

# of suspected spots by PCO: 4

# of spots PCO Confir: 0

ted Smith

in the master

bed room wall

suspected spots: 3

Confir spots: 1

Janet Ramsted

suspected spots: 0

Confir spots: 1 (by Abner)

# of spots PCO suspected: 0

# of spots PCO Confir: 0

Eric Fairmark's

Small cabin

suspected spots: 3

Confir spots: 2

# of spots PCO suspected: 6

# of spots PCO Confir: 1

Many nice turner

in the ceiling but

No turner both IR

& a window

Three spots of wood

area acoustic sensor

pickup in 2 day locat

in the room wall

House has Sathcon in

place since last year

term sign at the exact

Apr. but no life turner sign

IR did pick up

wet spot and

Acoustic sensor pickup

turner seen in the

kitchen & living room

wall down area

3000 + ft known

has a few Super spot

PCO suspected: 0

PCO Confir: 0

IR did not detect

acoustic - perhaps turner

around the

exterior wall

seeing

Acoustic - Yes



Date	Location	Type of Build	Observations
11/23/01	Bay St. Louis John PCO: NO WE: NO	Concrete build. (John) $\approx 1300$ ft <sup>2</sup> suspected spots: 1 actually confirm spots: 0 21 pco suspected spots: 0 2 spots pco conf. 0	Some termite mud tubes on outside wall & No termite signs in
11/24	Richy cabin between Bay St Louis & New Orleans WE: Yes PCO: <del>Yes</del> (for good pco)	Wooden cabin in & out $\approx 2000$ ft <sup>2</sup> equipped with every thing suspected spots: 6 confirm spots: 2 2 pco suspected spots: 2 1 of pco confirm: 1	only yard termite & 1) or two old unused crissack pole & water 2) or two new crissack pole that supporting the house. Some mud tubes Formosan termite
11/26	Chuck cabin next to Richy cabin WE: Yes PCO: NO	Very old wooden cabin $\approx 1200$ ft <sup>2</sup> suspected spots: 7 confirm spots: 3 2 of pco suspected spots 2 of pco confirm spots: 0	many termite on the outside under supports and found some IR sign on the wall & floor & ceiling
11/15	Near Royal Oak 50% NO 100% in the with 50% YES 100% NO with the same Jeff Hollarn Brick House $\approx 1700$ ft <sup>2</sup> suspected spots: 3 confirm spots: 0	Some Termite in spot near the fire place in but no termite activity No visual sign 2 pco suspected spots: 1 confirm: 0	



Location	Type of Building	Observations
<p>1/23 Pass Christian (Mason) <sup>①</sup> ✓ Add <sup>then</sup> PCO: ? Yes (masonry) <sup>2000</sup> We: Yes <sup>termites</sup></p>	<p>Constructed Old Wooden house 1800 ft<sup>2</sup> wooden wall in the whole house.</p>	<p>many termites in the attic were found (Hot) suspect spot: 7 confirm spot: 3 # of <del>prob</del> PCO suspicion spots: 3 # of spots confirm: 0</p>
<p>Mason <sup>②</sup> ✓ New <sup>House</sup> PCO: No We: NO House was sprayed all around each year the replaced wall was also re-sprayed</p>	<p>wooden frame brick outside ~ 2000 ft<sup>2</sup>  Suspected spot: 1 confirm spot: 0 # of spots PCO suspicion spots: 0 # of spots confirm: 0</p>	<p>House is under a very good PCO Contractor care, they pump the concrete slab whenever the found small cracks. PCO spray the whole outer wall soil. The <sup>North</sup> garage wall was found to be badly infested 6 months ago but was replaced with half concrete &amp; half 2' x 4" wall. &amp; the <sup>(upper)</sup> <sup>(lower)</sup> wall was sprayed with</p>
<p>2/23 Bay St. Louis (Bease) <sup>①</sup> PCO: NO (definitely) We: Yes</p>	<p>Wooden wall &amp; wooden siding ~ 3400 ft<sup>2</sup> old house but well maintained Suspected spots: 3 confirm spots: 2</p>	<p>House has no termite treatment  # of PCO suspicion spots: 0 # of spots confirm: 0</p>
<p>3/23 Michael Bay St. Louis PCO: NO (Probably) We: Yes</p>	<p>Very old suspected <sup>flow</sup> <sup>concrete</sup> <sup>work</sup> <sup>had to</sup> wood house <sup>look for</sup> <sup>and</sup> <sup>take</sup> <sup>out</sup> <sup>the</sup> ~ 1800 ft<sup>2</sup> # of PCO suspicion spots: 0 # of spots confirm: 0</p>	<p>concrete <sup>work</sup> <sup>had to</sup> <sup>look for</sup> <sup>and</sup> <sup>take</sup> <sup>out</sup> <sup>the</sup> concrete <sup>work</sup> <sup>had to</sup> <sup>look for</sup> <sup>and</sup> <sup>take</sup> <sup>out</sup> <sup>the</sup> found some termite <sup>work</sup> <sup>had to</sup> <sup>look for</sup> <sup>and</sup> <sup>take</sup> <sup>out</sup> <sup>the</sup> # of spots confirm: 0</p>

Date	Location	Type !! build Construction	Observation
11/12/01	Oxford Rare species ibn	Wood + Brick 2800 sq ft	IR: NO Acoustic: NO
	PCO: NO We: NO	Centric on the have more than a year ago suspected sp: 0 conf sp: 0 # of suspected sp: 0 # of sp: pco conf: 0	House has not been put in 10 years + ago but 3 months ago found termites to go outside house.
11/12/01	Oxford Diana West	Wood + Brick 1800 sq ft	IR from spot Acoustic (1) down corner + term sand (2) since sand in the mat bed 100 ft door
	We: Yes PCO: No (No sound off)	House was bought 3 mo ago suspected sp: 4 conf sp: 1 # of pco suspected sp: 0 # of sp: pco conf: 0	
11/13/01	Oxford Bob Hill	Wood & Brick House very close to wooded area I expect to see termites but suspected sp: 5 conf sp: 1 # of pco suspected sp: 1 # of sp: pco conf: 0	Rm Temp was 70° IR didn't detect found a few signs the second floor by but Acoustic Confirmed was a small found a evidence in the garage wall the wall that they the garage (good sand) Term to Yes
	We: Yes PCO: NO (probably No)		

Location	Type of build	Observation
Bay St. Ln Mac's Cabin WE: Yes PCO: 80% No	Construction wooden House old ~ 100yrs	<p>superficial spots: 2 confirm spots: 1 # of PCO Superficial spots: 2 # of PCO confirm: 1 <sup>only for dry wood</sup></p> <p>? : Termites 60% yes</p>
New orlean Mac's home PCO: No WE: Yes 80%	<p>superficial spots: 3 confirm spots: 1 (dry wood with a corner screw) # of PCO Superficial spots: 3 # of PCO confirm: 1</p> <p>TR: Some hot spot between children room &amp; external wall</p>	<p>Fire ant detected by accident</p>
Tupelo Lake front Sub division PCO: No WE: No	<p>superficial spots: 3 confirm spots: 0 Construction 2nd &amp; 3rd floor 2000 yrs</p>	<p># of PCO Superficial spots: 1 # of PCO confirm: 0 (No termites detected) The home owner found termites few weeks ago &amp; PCO treated the house 3 day before we inspected the house</p>

<p>Bernard JANSEN old house PCO: Yes Pest Control checked 10/4/2001 WE: Yes</p>	<p>2100 sq ft 1 bed room oak &amp; birch Construction type</p> <p>superficial spots: 5 confirm spots: 1 # of PCO superficial spots: 1 TR # of PCO confirm: 0</p>	<p>PCO Inspected on 10/4/2001 &amp; certified "No termites" but we found Termites in Master Bath &amp; daughter's closet (closed door place)</p> <p>+++ many small signs in master bath, Daughter's closet (Total: 3 locations)</p>
---	--	---

probably no - if yes, has to be due to the old damage

They probably say in the master bath instead of in the daughter's closet

Date	Location	Type of building Construction	Observations
12/28/61	Bay St. house Chuck Brotz Room PCO or Owner: NO WE: YES # of suspected spots: 3 # of spot PCO conf: 0	Suspected spot: 3 Carpenter spots: 1 old wooden house treated 3 years ago (many ants tented along) Owner put down bait (bought from window store) around the house 0.8 hr	Very well kept up we found <sup>some</sup> termite in the master bed room wall (2 across) saw a conifer from the outside of the house IR: +++ Yes = termite
12/21/61	Bay St. house Corker's house WE: NO PCO: NO	0.8 hr suspected spot: 1 3800 ft <sup>2</sup> 2 conf spot Suspected with 8' concrete pole of 100 suspected spot: 0 # of spots PCO confirm: 0	No signs of termite
12/17/61	Bay St. house Rich's Mother WE: YES PCO: YES	1000 ft <sup>2</sup> old wooden house 0.7 hr Suspected spots: 8 Carpenter spots: 4 # of PCO suspected spots: 0 # of spot PCO confirm: 0	IR: +++ many many termites on the ceiling + wall Acacia: 2 conf +++ many termites on the floor
12/28/61	Bay St. house Joe Dea WE: 60% yes PCO: YES	0.6 hr old wooden house Some suspected spots	Suspected spot: 4 Carpenter spots: 2 # of PCO suspected spots: 0 # of spot PCO confirm: 0

LOCATION	Type of Building Construction	Observation
8/10 Bay St Louis (Mississippi)	wooden wall + sheet brick. Common mid South construction	found termites in the outside wall wood piling with acoustic sensor. IR did not pick up any <del>sign</del> subterranean signs at all.
Ridley's House	~ 4000 sq ft Concrete slab Suspected sp: 3 Confid sp: 1	
We: Yes Pro: No (50% yes) for good pro	1 house # of pcc suspect sp: 1 # of sp pcc confid: 1 (50%)	Yes Port side with almost no signs IR: none in this spot

8/10 Bay St Louis Fritz Rogay House	wooden wall, floor wooden ceiling conventional foundation with supporting posts under cross space	Some suspension sp. I out of the door old. Some damage in the pole but no termites seen ?
We: NO 80% Pro: Yes (75%) Suspected sp: 2 Confid sp: 0	A very very fine house / contemporary houses) # of pcc suspect sp: 4 # of sp pcc confid: 0 11:55 - 12:00 pm	IR: saw 5 - 6 pcc spots

8/10 Bay St Louis C. G. C. Taylor	wooden wall, floor conventional foundation	inside temp was the same as outside. Before IR did not work too well But found termites on the third floor wood panel with Pencil: 6-8
We: Yes Pro: No (50% yes)	Suspected sp: 4 Confid sp: 2 (2nd floor) # of pcc suspect sp: 2 # of sp pcc confid: 1 (50%) 12:20 - 13:00	Yes

**This Page is Inserted by IFW Indexing and Scanning  
Operations and is not part of the Official Record**

**BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☒ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☒ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☒ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:**

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.**